

Oil Field Environmental Incident Summary

Incident: 20160505153328

Date/Time of Notice: 05/05/2016 15:33

Responsible Party: BuckhornEnergy

Well Operator: BUCKHORN ENERGY SERVICES, LLC

Well Name: Zimmerman SWD #1

Field Name: BUFORD

Well File #: 90254

Date Incident: 5/5/2016

Time Incident: 06:00

Facility ID Number:

County: WILLIAMS

Twp: 152

Rng: 104

Sec: 9

Qtr: SE NE

Location Description:

Submitted By: Nancy Roberts

Received By:

Contact Person: Nancy Roberts
5613 DTC Parkway Suite 800
Greenwood Village, CO 80111

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	Barrels				
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None - all leak was contained in dike

Areal Extent:

Potential Environmental Impacts:

None All leak was contained in impermeable dike

Action Taken or Planned:

Currently have isolated leak; will fix and will pick up all contaminated pea gravel.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 5/5/2016 ***Status:*** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, was contained within the diking according to the report. NDIC retains oversight.